



January 2025 Report

- Snow removal and salting continues as needed
- General shop maintenance as time permits
- Finished replacing remaining pins and bushings on loader
- Installed new cutting edge on 1 ton dump trucks snow plow
- Repaired electrical issues with back hoe. All lights and windshield wipers are now working properly
- Steamed cleaned 1 ton, loader and backhoe.
- Repaired skid plate on loader bucket
- The road crew responded to two different structure fires within the village, one on Maple St. and the other on Manchester. Response from the road crew was to ensure adequate salt was applied to the icy area created by the fire operations and to assist the FD with sifting through smoldering debris with the back hoe to expose hot spots to be extinguished.